

C of e

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:)
NOBUYUKI UCHIYAMA	: Examiner: Kevin Pyo)
Appln. No.: 10/611,929	: Art Unit: 2878
Filed: July 3, 2003	:)
For: IMAGE READING APPARATUS	Certificate APR 0 7 2006
U.S. Patent No.: 6,979,809 B2	of Correction
Issued: December 27, 2005	:) April 3, 2006

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

CERTIFICATE OF CORRECTION UNDER RULE 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

APR - 7 2006

Patentees' undersigned attorney may be reached in our New York office by telephone at (212) 218-2100. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

John A. Krause

Attorney for Patentee Registration No. 24,613

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
Facsimile: (212) 218-2200

560663v1

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

6,979,809 B2

DATED

December 27, 2005

INVENTOR(S) :

NOBUYUKI UCHIYAMA

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 5

Line 22, "setting," should read --settings,--.

COLUMN 7

Line 51, "setting," should read --settings,--.

COLUMN 10

Line 15, "the driving signal (second occurrence)" should be deleted.

MAILING ADDRESS OF SENDER:

PATENT NO. US 6,979,809 B2

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

No. of add'l. copies @ 30¢ per page

Form PTO 1050 (Rev. 3-82)

560663v1

APR - 7 2006

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

6,979,809 B2

DATED

December 27, 2005

INVENTOR(S) :

NOBUYUKI UCHIYAMA

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 5

Line 22, "setting," should read --settings,--.

COLUMN 7

Line 51, "setting," should read --settings,--.

COLUMN 10

Line 15, "the driving signal (second occurrence)" should be deleted.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. <u>US 6,979,809 B2</u>

No. of add'l. copies @ 30¢ per page

Form PTO 1050 (Rev. 3-82)

560663v1

